

## Rockies Express Pipeline LLC

## Preliminary REX 2024 Maintenance

Listed below is a summary of the planned outages that could affect segment and/or receipt/delivery point capacity. This schedule is not necessarily a complete list of all planned outages that may occur and is subject to change as time progresses to reflect any project delays, modifications, cancellations and/or additions. Additionally, the anticipated impacts and restrictions are subject to change.

Start Month	Start Date	Finish Date	Outage Duration	Segment	Flow Direction	Station/Location/Area	Explanation	Firm Primary at Risk
Sep-24	9/10/2024	9/10/2024	4 Hours	140	West to East	Echo Springs CS	Maintenance	Ν
Sep-24	9/10/2024	9/10/2024	8 Hours	250   240	Bidirectional	Bertrand CS	Maintenance	Y
Sep-24	9/10/2024	9/11/2024	2 Days	280   290	Bidirectional	Turney CS	Maintenance	Y
Sep-24	9/10/2024	9/12/2024	3 Days	340	East to West	St Paul CS	Maintenance	Y
Sep-24	9/12/2024	9/12/2024	12 Hours	260	West to East	Steele City CS	Maintenance	Y
Sep-24	9/24/2024	9/25/2024	2 Days	330	East to West	Bainbridge CS	Maintenance	Y
Sep-24	9/25/2024	9/25/2024	4 Hours	340	East to West	Vectren Eagle	Maintenance	Ν
Sep-24	9/25/2024	9/26/2024	2 Days	300	Bidirectional	Mexico CS	Maintenance	Y
Oct-24	10/1/2024	10/3/2024	3 Days	380	East to West	Washington Court House CS	Maintenance	Y
Oct-24	10/8/2024	10/8/2024	8 Hours	250	Bidirectional	Bertrand CS	Maintenance	Y
Oct-24	10/8/2024	10/8/2024	12 Hours	260	West to East	Steele City CS	Maintenance	Y
Oct-24	10/8/2024	10/13/2024	6 Days	380	East to West	Columbus CS	Maintenance	Y
Oct-24	10/9/2024	10/9/2024	12 Hours	260	West to East	Steele City CS	Maintenance	Y
Oct-24	10/10/2024	10/10/2024	12 Hours	260	West to East	Steele City CS	Maintenance	Y
Oct-24	10/15/2024	10/28/2024	14 Days	380	East to West	Chandlersville CS	Maintenance	Y
Oct-24	10/21/2024	10/28/2024	8 Days	280   290	Bidirectional	Turney CS	Equipment replacement	Y
Oct-24	10/29/2024	11/1/2024	4 Days	380	East to West	Chandlersville CS	Maintenance	Y
Nov-24	11/18/2024	11/25/2024	8 Days	280   290	Bidirectional	Turney CS	Equipment replacement	Y