



Tallgrass Interstate Gas Transmission LLC

Rolling 12 Month

Maintenance Plan

| Start Month | Start Date | Finish Date | Outage Duration | Segment | Station | Unit/Line | Explanation | Firm Primary at Risk |
|--------------------|-------------------|--------------------|------------------------|----------------|-----------------------|------------------|---------------------------|-----------------------------|
| Oct-2014 | 10/2/2014 | 10/2/2014 | 8 Hours | 420 | Lindsay/Madison | Pipeline | Line Lowering | N |
| Oct-2014 | 10/2/2014 | 10/2/2014 | 8 Hours | 215 | Lexington/Riverdale | Pipeline | Line Lowering | N |
| Oct-2014 | 10/9/2014 | 10/9/2014 | 8 Hours | 410 | St. Paul/Belgrade | Pipeline | Line Lowering | N |
| Oct-2014 | 10/9/2014 | 10/9/2014 | 12 Hours | 210 | Cozad/Lexington | Pipeline | Pipe Replacement | N |
| Oct-2014 | 10/16/2014 | 10/16/2014 | 8 Hours | 430 | Petersburg/Elgin | Pipeline | Line Lowering | N |
| Oct-2014 | 10/16/2014 | 10/16/2014 | 8 Hours | 430 | Elgin/Neligh | Pipeline | Line Lowering | N |
| Oct-2014 | 10/23/2014 | 10/23/2014 | 8 Hours | 410 | Belgrade/Albion | Pipeline | Line Lowering | N |
| Oct-2014 | 10/30/2014 | 10/30/2014 | 8 Hours | 210 | Ogallala/North Platte | Pipeline | Line Lowering | N |
| Oct-2014 | 10/30/2014 | 10/30/2014 | 8 Hours | 410 | Grand Island/St. Paul | Pipeline | Line Lowering | N |
| May-2015 | 5/19/2015 | 5/19/2015 | 6 Hours | 190 | Big Springs | Station | ESD Test and Calibrations | N |